

Safe Work Procedure – Delimber Operator

PERSONAL PROTECTIVE EQUIPMENT: Hi-vis Hardhat (to be worn when outside of machine)
Hearing Protection
Substantial Appropriate Footwear
Hi-vis Vest when off machine

PROCEDURES:

- Check to ensure machine is in safe operating condition before using.
- Ensure workers are clear of the hazardous area.
- Ensure guarding is being maintained.
- Maintain good housekeeping.
- Operate at a safe speed.
- Follow the lock-out or de-energization procedures while conducting maintenance work on the machine.
- Always enter and leave the machine in a safe manner. Use the handholds and beware of the slipping hazards that exist, particularly in the winter.
- Ensure a man-check system is set up while working alone.
- Ensure tracks are adequately caulked with ice lugs for winter operations.
- Wear the seat-belts when traveling.

ADDITIONAL SWP NOTES
